



U. S. Steel  
Clairton Works  
400 State Street  
Clairton, PA 15026-1855

March 27, 1996

Director, Air Toxics and Radiation Division  
U. S. EPA Region III  
841 Chestnut Street  
Philadelphia, PA 19107

SUBJECT: 1995 Summary Reports - Leak Detection and Repair of Equipment in  
Benzene Service - USS Clairton Works - Clairton, Pennsylvania

Dear Sir or Madam:

Enclosed please find two copies each of the following benzene NESHAPS monitoring reports:

- Leak Detection and Repair of Equipment in Benzene Service for the Period January 1995 through June 1995
- Leak Detection and Repair of Equipment in Benzene Service for the Period July 1995 through December 1995

These reports summarize the results of the monitoring of equipment in benzene service at USS Clairton Works for fugitive emissions. The reports have been prepared to satisfy the requirements promulgated by 40 CFR 61 Subparts L and V.

If you have any questions regarding this package, please call me at (412) 233-1101.

Very truly yours,

H. R. McCollum  
Manager, Environmental Control

HRM/kb-96088  
Enclosures

U. S. Steel Group  
A unit of USX Corporation



ED\_002508A\_00000399-00001